

EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone: (856) 303-2500 Fax: (856) 858-4571 Email: EnvChemistry2@emsl.com

Attn:

Nathanael Roberts TTI Environmental Inc. 1253 North Church Street Moorestown, NJ 08057

Phone: (856) 840-8800 Fax: (856) 840-8815

The following analytical report covers the analysis performed on samples submitted to EMSL Analytical, Inc. on 6/10/2022. The results are tabulated on the attached data pages for the following client designated project:

22-666 Admin Building

The reference number for these samples is EMSL Order #012209478. Please use this reference when calling about these samples. If you have any questions, please do not hesitate to contact me at (856) 303-2500.

Approved By:

Owen McKenna, Chemistry Laboratory Director



The test results contained within this report meet the requirements of NELAP and/or the specific certification program that is applicable, unless otherwise noted.

NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, CA ELAP 1877

The samples associated with this report were received in good condition unless otherwise noted. This report relates only to those items tested as received by the laboratory. The QC data associated with the sample results meet the recovery and precision requirements established by the NELAP, unless specifically indicated. All results for soil samples are reported on a dry weight basis, unless otherwise noted. This report may not be reproduced except in full and without written approval by EMSL Analytical, Inc.

6/30/2022



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077 Phone/Fax: (856) 303-2500 / (856) 858-4571

http://www.EMSL.com EnvChemistry2@emsl.com

EMSL Order: CustomerID: CustomerPO:

012209478 TTIE54

ProjectID:

Attn: **Nathanael Roberts** TTI Environmental Inc. **1253 North Church Street** Moorestown, NJ 08057

Phone: (856) 840-8800 Fax: (856) 840-8815 Received: 6/10/2022 09:45 AM

Project: 22-666 Admin Building

Analytical Results

		Allalytical	results					
Client Sample Description ADM-WC-HDS-1			Collected: 6/10/2022 7:20:00 AM				012209478-0001	
Method	Parameter	Result	RL Units		Prep Date & Analyst		Analysis Date & Analyst	
METALS								
200.8	Lead	ND	1.00 µg/L		6/23/2022	VD	6/23/2022 23:39	VD
Client Sample Description ADM-SF-2FBR-3			Collected:	6/10/2022 7:22:00 AM	Lab ID:		012209478-0002	
Method	Parameter	Result	RL Units		Prep Date & Analyst		Analysis Date & Analyst	
METALS								
200.8	Lead	ND	1.00 μg/L		6/23/2022	VD	6/23/2022 23:41	VD
Client Sample Description ADMWC-2FBR-4			Collected:	6/10/2022 7:22:00 AM		ID:	012209478-0003	
Method	Parameter	Result	RL Units		Prep Date & Analyst		Analysis Date & Analyst	
METALS								
200.8	Lead	ND	1.00 µg/L		6/23/2022	VD	6/23/2022 23:43	VD

Definitions:

MDL - method detection limit

J - Result was below the reporting limit, but at or above the MDL

ND - indicates that the analyte was not detected at the reporting limit

RL - Reporting Limit (Analytical)

D - Dilution Sample required a dilution which was used to calculate final results