

Eurofins Environment Testing Northeast LLC

Eurofins Edison

Lab Job ID: 460-318104-1
Job Description: 24-812 Orange BOE
For:
TTI Environmental Inc
1253 North Church Street
Moorestown, New Jersey 08057

Client ID	NJ Pri-Sec			Field Blank			OAE-BF-HGYM-1			OAE-BF-HGYM-2			OAE-BF-H125-3			OAE-BF-HNSE-4		
Lab Sample ID	Drinking Water			460-318104-1			460-318104-2			460-318104-3			460-318104-4			460-318104-5		
Sampling Date	Standards			12/17/2024 00:00:00			12/17/2024 06:16:00			12/17/2024 06:16:00			12/17/2024 06:18:00			12/17/2024 06:19:00		
Matrix				Water			Water			Water			Water			Water		
Unit																		
				Result	Q	MDL	Result	Q	MDL	Result	Q	MDL	Result	Q	MDL	Result	Q	MDL
WATER BY 200.8/200_DW_PREP(UG/L)																		
Lead	15			0.25	U	0.25	0.25	U	0.25	0.25	U	0.25	0.25	U	0.25	0.25	U	0.25

Highlighted Concentrations: Sample fails - results do not meet NJ State Primary/Secondary Drinking Water Requirements.
J : Result is less than the RL but greater than or equal to the MDL and the concentration is an approximate value.
U : Indicates the analyte was analyzed for but not detected.

Lab Contact:
Warleny Infante
Project Management Assistant I
(732)549-3900

Eurofins Environment Testi
Eurofins Edison
Lab Job ID: 460-318104-1
Job Description: 24-812 Orange BOE
For:
TTI Environmental Inc
1253 North Church Street
Moorestown, New Jersey 08057

Client ID	OAE-SF-NSE-5			OAE-SF-FAC-6			#N/A			OAE-BF-HEL-8			OAE-BF-HW6-9			OAE-BF-HW6-10		
Lab Sample ID	460-318104-6			460-318104-7			460-318104-8			460-318104-9			460-318104-10			460-318104-11		
Sampling Date	12/17/2024 06:20:00			12/17/2024 06:23:00			12/17/2024 06:22:00			12/17/2024 06:21:00			12/17/2024 06:25:00			12/17/2024 06:25:00		
Matrix	Water			Water			Water			Water			Water			Water		
Unit																		
	Result	Q	MDL	Result	Q	MDL	Result	Q	MDL	Result	Q	MDL	Result	Q	MDL	Result	Q	MDL
WATER BY 200.8/200_DW_PREP(UG/L)																		
Lead	64.3		0.25	1.3	J	0.25	0.25	U	0.25	0.25	U	0.25	0.25	U	0.25	0.25	U	0.25

Highlighted Concentrations: Sample fails - r
J : Result is less than the RL but greater thar
U : Indicates the analyte was analyzed for b

Lab Contact:
Warleny Infante
Project Management Assistant I
(732)549-3900

Eurofins Environment Testi
Eurofins Edison

Lab Job ID: 460-318104-1
Job Description: 24-812 Orange BOE
For:
TTI Environmental Inc
1253 North Church Street
Moorestown, New Jersey 08057

Client ID	OAE-BF-HR6-11			OAE-BF-H11a-12		
Lab Sample ID	460-318104-12			460-318104-13		
Sampling Date	12/17/2024 06:26:00			12/17/2024 06:28:00		
Matrix	Water			Water		
Unit						
	Result	Q	MDL	Result	Q	MDL
WATER BY 200.8/200_DW_PREP(UG/L)						
Lead	0.25	U	0.25	0.25	U	0.25

Highlighted Concentrations: Sample fails - r
J : Result is less than the RL but greater than
U : Indicates the analyte was analyzed for b

Lab Contact:
Warleny Infante
Project Management Assistant I
(732)549-3900